ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	15	T Dasarahalli
Street ID	**Street Name**	**Significant Landmark**
W0057, W0024, W0080, W0081, W0061, W0012, W0048, W	NA, 14th Crs, Om Shakthi Lyt 7th Crs	Ganesha Saw Mill
Segment No.	**Total Length (m)**	
15/C-W0057/S062339	812.87	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	24.01	77.511016	13.044979	77.510804	13.045041	Ganesha Saw Mill road	Deadend
2	140.29	77.511067	13.044971	77.512306	13.044608	Ganesha Saw Mill road	Kannada Kasthuri Road (W0081)
3	143.57	77.510911	13.044422	77.512201	13.044132	Ganesha Saw Mill road	Kannada Kasthuri Road (W0081)
4	109.96	77.511684	13.047526	77.511960	13.048483	1st Main Road	Ward Boundary
5	395.04	77.510753	13.044020	77.511660	13.047477	NH4	1st Main Road

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements and Re-Asphalting to Ganesha Saw Mill road and surrounding roads in Dasarahalli Ward No.15	4000000	2020
Year	**Type of Work**	**Other Work Type**
2020 - 2021	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Tender		015-20-000107
Work Order No.	**Work Order Date**	**Period of Extention**
EE/DD/WO/03/2022-23	20/04/2022	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
02/06/2022	01/06/2023	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಟಿ. ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

eld Inspection Details

Number of Trees	Any Other Information	Name
0		Archana

Date of Inspection	Remarks
02/06/2022	

Category	Image	Photo Remark
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Segment End		Location was not determined.
Segment End		Location was not determined.
Segment Start		Location was not determined.
Segment Start		Location was not determined.

Zone: DASARAHALLI **Ward No:** 15 **Ward Name:** T Dasarahalli **Street ID:** W0057, W0024, W0080, W0081,

ಸಹಾಯಕ ಕಂದಾಯ ಅಧಿಕಾರಿ
ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬೆಂಗಳೂರು, ಪೂರ್ವ
ಬೆಂಗಳೂರು

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	CE DAS	02/06/2022	02/07/2022	APPROVED
EE	EE DAS	02/06/2022	02/07/2022	COMPLETED
AEE	Ranganath B R	02/06/2022	02/07/2022	Completed
AE	Archana	02/06/2022	02/07/2022	Completed
AE	Archana	02/06/2022	02/07/2022	Completed

Forwarded to AE/Ward-15

ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರು
ಟಿ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

Zone: DASARAHALLI Ward No: 15 Ward Name: T Dasarahalli Street ID: W0057, W0024, W0080, W0081,